



# Lec 2: Technical Drawing

Review of technical drawing


1. Orthographic projection
2. Isometric projection
3. Sectioning
4. Dimensioning




Front





Right







Front



Bottom



# Orthographic drawing: threads




[Earle, 1992]

**Recommended styles**



### 3. Isometric (3D) Projection

- Coordinate system
- Drawing conventions





Line:

All lines parallel to x, y, z axes

Circle:


- Draw a circumscribing square
- Blend in with an ellipse

# Practice



Line: All lines parallel to x, y, z axes  
Circle: - Draw a circumscribing square  
- Blend in with an ellipse


1	1	BODY	CAST IRON
2	2	ROUND HEAD MACHINE SCREW	#4-48UNF X .250
3	1	PLATE	ALUMINIUM
4	1	SHAFT	STEEL
5	1	WOODRUFF KEY	
6	1	RETAINER	STEEL
7	3	ROUND HEAD MACHINE SCREW	#10-32UNF X .500
8	1	ARM	STEEL
9	1	HEX HEAD NUT	.375-24UNF



BUTTERFLY VALVE

# 4. Sectioning



- Why: view internal features or profile
- Techniques
  - Complete
  - Partial
  - Zig-zag
  - Rotate



# 4. Sectioning

1. Choose a view for sectioning
2. Mark the cutting plane with bold lines
3. Draw arrows to indicate viewing direction
4. Draw the sectioned view, and name it (optional)
5. Add cross-hatching pattern to cut areas


Inside features are hidden in standard view






## Sectioning rules:



- Hatching lines stop at solid lines
- Use different hatch angles for different parts
- Avoid sectioning a solid part






HOLE TAPPED THROUGH



TAP DRILL SHOWN








Front




Right

Section




1. Choose a view for sectioning
2. Mark the cutting plane with bold lines
3. Draw arrows to indicate viewing direction
4. Draw the sectioned view, and name it (optional)
5. Add cross-hatching pattern to cut areas






**3-4**

# 5. Dimensioning: rules





Material: 1020 steel

Unit: mm



# 5. Dimensioning: rules

- Specify unit.
- Use guideline to extend feature, leave a gap to the main drawing.
- Write dimension between arrows or tic marks.
- All lines must be parallel to x, y, z axes or part feature.
- Label diameter with "Ø" and radius with "R"




Material : Aluminum  
Units : inches  
Tolerance:  $\pm 0.010$

# 3. Effect of manufacturing processes

Process	Tolerance (in)	Finish Ra ( $\mu\text{in}$ )
Sand casting	$\pm 0.0500$	500-1000
...		
Turning	$\pm 0.0020$	15-250
...		
Grinding	$\pm 0.0003$	5-75

# Contact type: protractor



Source:  
<http://www.starrett.com/>

# Contact type: caliper

*Dial caliper*

*Vernier caliper*





# Contact type: height gage



*Digital*

*Vernier*

*Dial*

# Contact type: indicator



560-031



*dial*

*digital*


# Contact type: micrometer



# Non-contact type: optical comparator (profile projector)



# Non-contact type: measuring microscope



# Non-contact type: profile laser scanner



# Contact type: coordinate measuring machine (CMM)




<http://www.mitutoyo.com>

# Contact type: form measurement





Source: <http://www.taylor-hobson.com/>







# Non-contact type: laser sensor

Measuring the runout of an HDD



# Semi-contact type: Scanning probe microscopy



Iodine atoms in a  $3 \times 3$  array adsorbed on platinum. Data from Dr. Bruce Schardt, Purdue University.

# Contact type: surface profile measurement (profilometer)



# Equipment

## Contact type: Profilometer



[[www.processinstruments.ca](http://www.processinstruments.ca)]


# Equipment

## Noncontact type: interferometer




Source:  
<http://www.zygo.com/?/met/profilers/newview7000/>

# 6. Caliper




Dial caliper




Vernier caliper



Digital caliper



# Vernier scale reading




$$43.0 + 8(0.1) = 43.8 \text{ mm}$$

Reading: \_\_\_\_\_ mm (1 decimal digit)




# Vernier Caliper



$$0.700 + 2(0.025) + 9(0.001) = 0.759 \text{ in}$$

Reading: \_\_\_\_\_ in (3 decimal digits)


# Vernier Caliper



Reading: \_\_\_\_\_ in (3 decimal digits)




# Dial Caliper



$$3(0.1) + 12(0.001) + 0.0005 = 0.3125 \text{ inch}$$

*Reading: \_\_\_\_\_ inch (4 decimal digits)*


# Dial caliper



$$1(0.1) + 97(0.001) = 0.1970 \text{ inch}$$

*Reading: \_\_\_\_\_ inch (4 decimal digits)*


# Dial caliper



$$14 + 0.3 + 0.01 = 14.31 \text{ mm}$$

*Reading: \_\_\_\_\_ mm (2 decimal digits)*

# Dial caliper



$$13 + 0.40 + 1(0.02) + 0.01 = 13.43 \text{ mm}$$

*Reading: \_\_\_\_\_ mm (2 decimal digits)*




# 7. Micrometer








Micrometer set for different ranges




# Micrometer



*Range:*

*Reading:* \_\_\_\_\_ *inch (4 decimal digits)*


# Micrometer



*Range:*

*Reading:* \_\_\_\_\_ *inch (4 decimal digits)*


Metric  
micrometer



*Range:*

*Reading:* \_\_\_\_\_ *mm (3 decimal digits)*

Metric  
micrometer



*Range:*

*Reading:* \_\_\_\_\_ *mm (3 decimal digits)*


# *Micrometer Reading*

- 1) DVD (comes with the reference textbook)
- 2) Lab practice
- 3) Homework
- 4) Online practice


- <http://www.linnbenton.edu/auto/day/mike/vernier3.html>
- <http://www.pastaffing.com/trainmic.asp>
- <http://cf.linnbenton.edu/eit/auto/krolicp/web.cfm?pgID=2262>
- <http://www.wisc-online.com/Objects/ViewObject.aspx?ID=MTL1902>

# 8. Indicators

- Amplify small displacement (linear or rotation)
- Measure dimensional change or form variation



# Indicator applications




10.14.2008

02.10.2009



## *Indicator*

- Assume rotation directions
- Range: 0-1 inch
- Marker: 0.001 inch
- Read small dial then large dial




*Reading: \_\_\_\_\_ (4 decimal digits)*

$$2(0.1) + 33.2(0.001) = 0.2332 \text{ inch}$$

# 9. Profile projector (optical comparator)


- Magnify image
- Analyze shadow
- Calculate true



*Customized template*



# Angle measurement




*Angle measurement and conversion*  
 $1^\circ = 60 \text{ minutes} = 3600 \text{ seconds}$

$28^\circ 15 \text{ min}$

$28 + 15/60 = 28.25^\circ$

# 10. Coordinate measuring machine (CMM)

- Use precise probes with known dimensions
- Provide coordinate of each point
- Calculate dimension and form



# 10. Coordinate measuring machine (CMM)

*3-DOF probe*




*5-DOF probe*



# RET Lec 3: Engineering Materials

- 1) Nature of material
- 2) Mechanical properties
- 3) Effect of temperature
- 4) Metals
- 5) Polymers
- 6) Material comparison
- 7) Effect on manufacturing





Engineering materials: metal, ceramic, polymer

Natural materials: wood, clay, rock, bone...

# 1. Nature of material

## □ Atom

Atom = nucleus + electrons




<http://www.vtaide.com/png/atom.htm>

Bonds: strong primary:  
weak secondary:


Break bonds → release atoms (machining)




Crystalline



Polycrystalline



Amorphous



[en.wikipedia.org](http://en.wikipedia.org)


## Crystalline structure

- ordered
- 3D
- metals, ceramics


## Amorphous structure

- random
- 3D
- polymers, ceramics


# Common crystalline structures




BCC



FCC



HCP



Diamond

## 2. Mechanical property of material

### 2.1. Stress and strain

Normal stress  $\sigma = \frac{F}{A}$

Shear stress  $\tau = \frac{F_s}{A_s}$

Small strain  $\varepsilon = \frac{\Delta L}{L} = \frac{L_f - L_i}{L_i}$

Large strain  $\varepsilon = \ln \frac{L_f}{L_i}$


Shear strain  $\gamma$

# Units

	US customary	SI (Metric)
Mass	pound: lb	g, kg
Force	pound: lb	Newton (N)
Length	in, ft	m, cm, mm
Area	in <sup>2</sup> , ft <sup>2</sup>	m <sup>2</sup> , cm <sup>2</sup> , mm <sup>2</sup>
Strain & shear strain		
Stress & strength		

## 2.2. Tensile test

- Increase force till breaking
- Force is 90° to fractured surface



The ultimate tensile stress (material strength, maximum normal stress) is

$$\sigma_{\max} = \frac{F_{\max}}{A} = S_u$$




TABLE 3.2 Yield strength and tensile strength for selected metals.


Metal	Yield Strength		Tensile Strength		Metal	Yield Strength		Tensile Strength	
	MPa	(lb/in. <sup>2</sup> )	MPa	(lb/in. <sup>2</sup> )		MPa	(lb/in. <sup>2</sup> )	MPa	(lb/in. <sup>2</sup> )
Aluminum, annealed	28	(4,000)	69	(10,000)	Nickel, annealed	150	(22,000)	450	(65,000)
Aluminum, CW <sup>a</sup>	105	(15,000)	125	(18,000)	Steel, low C <sup>a</sup>	175	(25,000)	300	(45,000)
Aluminum alloys <sup>a</sup>	175	(25,000)	350	(50,000)	Steel, high C <sup>a</sup>	400	(60,000)	600	(90,000)
Cast iron <sup>a</sup>	275	(40,000)	275	(40,000)	Steel, alloy <sup>a</sup>	500	(75,000)	700	(100,000)
Copper, annealed	70	(10,000)	205	(30,000)	Steel, stainless <sup>a</sup>	275	(40,000)	650	(95,000)
Copper alloys <sup>a</sup>	205	(30,000)	410	(60,000)	Titanium, pure	350	(50,000)	515	(75,000)
Magnesium alloys <sup>a</sup>	175	(25,000)	275	(40,000)	Titanium alloy	800	(120,000)	900	(130,000)

TABLE 3.3 Ductility as percent elongation (typical values) for various selected materials

Material	% elongation	Material	% elongation
<b>Metals</b>		<b>Metals, continued</b>	
Aluminum, annealed	40	Steel, low C <sup>a</sup>	30
Aluminum, cold worked	8	Steel, high C <sup>a</sup>	10
Aluminum alloys, annealed <sup>a</sup>	20	Steel, alloy <sup>a</sup>	20
Aluminum alloys, heat treated <sup>a</sup>	8	Steel, stainless, austenitic <sup>a</sup>	55
Aluminum alloys, cast <sup>a</sup>	4	Titanium, nearly pure	20
Cast iron, gray <sup>a</sup>	0.6	Zinc alloy	10
Copper, annealed	45	<b>Ceramics</b>	0
Copper, cold worked	10	<b>Polymers</b>	
Copper alloy: brass, annealed	60	Thermoplastic polymers	100
Magnesium alloys <sup>a</sup>	10	Thermosetting polymers	1
Nickel, annealed	45	Elastomers (e.g., rubber)	1

## 2.3. Shear test

- Increase force till breaking
- Force is parallel to fractured surface



The ultimate shear stress (or material shear strength, or maximum shear stress) is:

$$\tau_{\max} = \frac{P_{\max}}{A_s} = S_s$$




# Tensile/shear tester

<http://mee-inc.com/services-laboratory.html>



tensile



shear


## 2.4. Hardness testers



<http://www.all-testers.com/hardness-testers.php>



<http://www.brystartools.com>




<http://www.classoneequipment.com>


## 2.4. Hardness test

- Force an indenter @ preset force, time
- Measure indentation
- Calculate hardness (Brinell, Vicker, Knoop, Rockwell...)
- Link to material strength

Vickers Method



Brinnell Method





Diamond indenter

Steel sphere indenter


Size of depression created by the tool is a measure of hardness

Polished surface of widget



$$H_{\text{Vicker}} = \frac{1.854 F}{D^2}$$

Su



# 3. Effects of temperature




Hot  
soft  
ductile



Cold  
hard  
brittle

Mechanical  
properties



Temperature


# 4. Metals

Alloy = mixture of different atoms


Composite = mixture of different materials (visibly different)



# 4.2. Ferrous metals



# 4.2.1. Steels



## □ Nomenclature

1015 steel: 0.15% C, Fe (balance)

4140 steel: 0.40% C, 1% Cr, 0.8% Mn, 0.2% Mo, Fe (balance)



Pro's: Good tension & compression ...



Con's: High density, corrosive ...

# Stainless Steels

## ☐ Types

- Austenitic
- Ferritic
- Martensitic
- PH
- Duplex


## ☐ Pro's and Con's

- 😊 Corrosion resistant...
- 😞 High density, more expensive ...





# 4.2.2 Cast iron



## □ Types

- Gray
- White
- Ductile




Easy to machine, cast, damping...



Rust, heavy, good compression but poor tension...


# Effects of carbon content

- Optimal carbon  $\rightarrow$  strengthen alloy
- Too much carbon  $\rightarrow$  weaken alloy






**Gray cast iron with graphite flake**



**Malleable cast iron**



**Nodular cast iron**

# 4.3. Nonferrous metals

## 4.3.1 Aluminum

- Wrought: ductile, can be deformed significantly  
XXXX-Tx
- Cast: brittle, can be cast easily  
Axxx-Tx
- Pro's and Con's



Light, min corrosion, easy to machine



\$ more, softer, lower strength (against steel)



Aluminum fuselage of a Boeing 747  
Source: <http://en.wikipedia.org/wiki/Fuselage>

# 4.3. Nonferrous metals

## 4.3.2 Copper

- CA XXX



High conductive, soft (easy to fabricate)...



Lower strength (against steel), corrosive...

# 4.4 Super alloys

☐ Types: Fe, Ni, Co based alloys: Rene, Incoloy, Inconel, Stellite, Hastelloy, Monel ...

😊 Pro's & Con's

😞 Maintain high strength, hardness at high temperature  
\$\$, heavy, difficult to manufacture





Source: <http://www.afterburner.nl/lossie/>

# 5. Polymers

- ❑ Basic elements: C, H, O, N
- ❑ Polymerization: combine carbons and others to chain molecules.





More crystallinity  $\rightarrow$  metal like

Linear chain

branching

cross-linking



## □ Types

- Thermoplastics Repeat heating/cooling, linear chains
- Thermoset Heat/cool once, cross-linked chains
- Elastomers Stretch  $>10x$ , coiled chains

## □ Pro's & Con's



- + Low  $T_m$  for processing
- + High ductility
- + Light
- + No rust




- Temp limited
- Low strength, hardness
- Degraded by UV light
- Nonconductive



Natural materials: wood, rock, sand, clay, bone...

## Wood as engineering material

- Hardwoods from deciduous trees (e.g. ash, beech, birch, mahogany, maple, oak, teak, and walnut).
- Softwoods from evergreen (coniferous) trees (e.g. cedar, cypress, fir, pine, spruce, and redwood).



- Wood is anisotropic. Its strength depends on loading directions (along or across the grains), or content of moisture /chemical treatment.



# Wood cutting



## NORTH AMERICAN HARDWOODS

Wood Species	Specific Gravity*	Compressive Strength (psi)	Bending Strength (psi)	Stiffness (Mpsi)	Hardness (lb)
Alder, Red	0.41	5,820	9,800	1.38	590
Ash	0.60	7,410	15,000	1.74	1,320
Aspen	0.38	4,250	8,400	1.18	350
Basswood	0.37	4,730	8,700	1.46	410
Beech	0.64	7,300	14,900	1.72	1,300
Birch, Yellow	0.62	8,170	16,600	2.01	1,260
Butternut	0.38	5,110	8,100	1.18	490
Cherry	0.50	7,110	12,300	1.49	950
Chestnut	0.43	5,320	8,600	1.23	540
Elm	0.50	5,520	11,800	1.34	830
Hickory	0.72	9,210	20,200	2.16	†
Maple, Hard	0.63	7,830	15,800	1.83	1,450
Maple, Soft	0.54	6,540	13,400	1.64	950
Oak, Red	0.63	6,760	14,300	1.82	1,290
Oak, White	0.68	7,440	15,200	1.78	1,360
Poplar	0.42	5,540	10,100	1.58	540
Sassafras	0.46	4,760	9,000	1.12	†
Sweetgum	0.52	6,320	12,500	1.64	850
Sycamore	0.49	5,380	10,000	1.42	770
Walnut	0.55	7,580	14,600	1.68	1,010


## NORTH AMERICAN SOFTWOODS

Wood Species	Specific Gravity*	Compressive Strength (psi)	Bending Strength (psi)	Stiffness (Mpsi)	Hardness (lb)
Cedar, Aromatic Red	0.47	6,020	8,800	0.88	900
Cedar, Western Red	0.32	4,560	7,500	1.11	350
Cedar, White	0.32	3,960	6,500	0.80	320
Cypress	0.46	6,360	10,600	1.44	510
Fir, Douglas	0.49	7,230	12,400	1.95	710
Hemlock	0.45	7,200	11,300	1.63	540
Pine, Ponderosa	0.40	5,320	9,400	1.29	460
Pine, Sugar	0.36	4,460	8,200	1.19	380
Pine, White	0.35	4,800	8,600	1.24	380
Pine, Yellow	0.59	8,470	14,500	1.98	870
Redwood	0.35	5,220	7,900	1.10	420
Spruce, Sitka	0.40	5,610	10,200	1.57	510

[http://workshopcompanion.com/KnowHow/Design/Nature\\_of\\_Wood/3\\_Wood\\_Strength/3\\_Wood\\_Strength.htm](http://workshopcompanion.com/KnowHow/Design/Nature_of_Wood/3_Wood_Strength/3_Wood_Strength.htm)

- Wood is anisotropic. Its strength depends on loading directions (along or across the grains), or content of moisture /chemical treatment.

## How does wood compare? (Tensile strength)



# 6. Comparison

## Mechanical properties of selected materials

Materials	$S_u$ (ksi)	$\epsilon_f$ (%)
Gray cast iron	22 (tensile) 83 (compressive)	~0 ~0
2024-O aluminum	27	22
2024-T3	70	16
1050 steel –anneal	92	24
1050 steel – heat treat	163	9
Polypropylene	4	10-1000



# Material ↔ Manufacturing

## *Mat'l property*

## *Affected process*

■ Thermal: melting temp

*casting, welding, molding*

■ Mechanical: strength

hardness, ductility

*machining, forming*

■ Chemical: oxidation

*etching, welding*

■ Metallurgical: alloying

*heat-treating, machining*

## Lecture 04


# Metal forming & stamping

1. Material behavior
2. Effect of temperature
3. Review
4. Bulk forming processes
  - Rolling
  - Forging
  - Explosive forming
  - Extrusion
  - Wire drawing
5. Stamping processes
  - Shearing & cutting
  - Bending
  - Drawing
  - Lancing
  - Rubber forming
  - Embossing

# Art: Vulcan forging the armour of Achilles


By: Giulio Romano  
(1499 - 1546)






# 1. Material behavior

# 2. Effect of temperature



# 5. Stamping

	Thickness (mm)	(in)
Plate	$t > 6.0$	$t > 0.250$
Sheet	$5.9 > t > 0.4$	$0.249 > t > 0.015$
Foil	$0.3 > t > 0.02$	$0.014 > t > 0.000,8$



# Metal sheet thickness

Sheet Metal Gauge Guide




Gauge	Steel (mm)	Galvanized (mm)	Stainless (mm)	Aluminum (mm)
3	0.2391 (6.07)	--	--	--
4	0.2242 (5.69)	--	--	--
5	0.2092 (5.31)	--	--	--
6	0.1943 (4.94)	--	--	0.162 (4.1)
7	0.1793 (4.55)	--	0.1875 (4.76)	0.1443 (3.67)
8	0.1644 (4.18)	0.1681 (4.27)	0.1719 (4.37)	0.1285 (3.26)
9	0.1495 (3.80)	0.1532 (3.89)	0.1563 (3.97)	0.1144 (2.91)
10	0.1345 (3.42)	0.1382 (3.51)	0.1406 (3.57)	0.1019 (2.59)
11	0.1196 (3.04)	0.1233 (3.13)	0.1250 (3.18)	0.0907 (2.30)
12	0.1046 (2.66)	0.1084 (2.75)	0.1094 (2.78)	0.0808 (2.05)
13	0.0897 (2.28)	0.0934 (2.37)	0.0940 (2.40)	0.0720 (1.80)
14	0.0747 (1.90)	0.0785 (1.99)	0.0781 (1.98)	0.0641 (1.63)
15	0.0673 (1.71)	0.0710 (1.80)	0.0700 (1.80)	0.0570 (1.40)
16	0.0598 (1.52)	0.0635 (1.61)	0.0625 (1.59)	0.0508 (1.29)
17	0.0538 (1.37)	0.0575 (1.46)	0.0560 (1.40)	0.0450 (1.10)
18	0.0478 (1.21)	0.0516 (1.31)	0.0500 (1.27)	0.0403 (1.02)
19	0.0418 (1.06)	0.0456 (1.16)	0.0440 (1.10)	0.0360 (0.91)
20	0.0359 (0.91)	0.0396 (1.01)	0.0375 (0.95)	0.0320 (0.81)
21	0.0329 (0.84)	0.0366 (0.93)	0.0340 (0.86)	0.0280 (0.71)
22	0.0299 (0.76)	0.0336 (0.85)	0.0310 (0.79)	0.0250 (0.64)
23	0.0269 (0.68)	0.0306 (0.78)	0.0280 (0.71)	0.0230 (0.58)
24	0.0239 (0.61)	0.0276 (0.70)	0.0250 (0.64)	0.0200 (0.51)
25	0.0209 (0.53)	0.0247 (0.63)	0.0220 (0.56)	0.0180 (0.46)
26	0.0179 (0.45)	0.0217 (0.55)	0.0190 (0.48)	0.0170 (0.43)
28	0.0149 (0.38)	0.0187 (0.47)	0.0160 (0.41)	0.0126 (0.32)

Star sheet







# 5.1 Stamping: shearing




Sheared zone



Fractured zone



(a)



(b)

Shearing analysis: force  $F$ ? power  $P$ ?

$$P = FV \quad (\text{since } F//V)$$

$F_s$ : shearing force

$A_s$ : sheared area


$S_s$ : shear strength

$S_u$ : tensile strength


$P$ : power

$v$ : speed


# 5.2 Stamping: bending




Straight flanging




stretch flanging




shrink flanging



Hemming





seaming



curling

# 5.2 Stamping: bending




# Bending analysis:

shearing force  $F$ , power  $P$ ?


$$P = FV \quad (\text{since } F // V)$$

$$F = \frac{KS_u wt^2}{D}$$


$F$ : bending force  
 $S_u$ : tensile strength  
 $w$ : sheet width  
 $t$ : sheet thickness  
 $D$ : die opening  
 $K$ : constant



Pressure pad



# 5.2 Stamping: spring back



<http://www.custompartnet.com/wu/sheet-metal-forming>

<http://riiskadesign.com/spring-back-bankers-chair>

## Springback


- Elastic recovery
- Unavoidable
- Correctable

## Correction

- Overbending
- Bottoming
- Annealing



## 5.2 Stamping: bend allowance

- Starting dimension before bending
- Small bending radius  $\rightarrow$  stretching rod/sheet
- Correct with bending allowance





# 5.3 Stamping: (cup) drawing




# Cup drawing analysis: force F? power P?

$$F_h = 0.015\pi S_y \left[ D_b^2 - (D_p + 2.2t + 2R_d)^2 \right]$$


$$F = \pi D_p t S_u \left( \frac{D_b}{D_p} - 0.7 \right)$$

$$P = FV \quad (\text{since } F \ll V)$$


F: drawing force  
 $F_h$ : holding force  
 $S_y, S_u$ : yield, tensile strength  
 $D_b, D_p$ : blank, punch diameter  
 $t$ : sheet thickness  
 $R_d$ : die radius




# Cup drawing defects




(a)




(b)



(c)





(d)



(e)




# 5.4 Stamping: lancing





# 5.5 Stamping: rubber (Guerin) forming

- ✓ Simpler than cup drawing, forging, lower cost, prototyping
- Wear/tear of rubber, simple shape only, thin sheet only




# 5.6 Stamping: embossing

- To deform and form raised/indented features on thin sheet.
- Another version of forging, rolling, or cup drawing



www.quia.com



www.yuri-roll.co.jp

# Lec 5: Material Removal Processes

## A. Traditional techniques

### A1. Overview and machining theory

A1.1 Chip formation

A1.2. Mechanics of machining

### A2. Processes

A2.1. Lathe operations

A2.2. Mill and drill operations

A2.3. Other operations

A2.4. Process planning

A2.5. Cutting tools and cutting fluids

## B. Nontraditional techniques

### B1. Overview

### B2. Processes

B2.1. Water jet and abrasive water jet

B2.2. Electrochemical machining

B2.3. Electrical discharge machining

B2.4. Energy beam machining

B2.5. Chemical etching and photochemical etching

## C. Finishing techniques

### C1. Overview

### C2. Processes

C2.1. Grinding and honing


C2.2. Lapping

C2.3. Polishing

C2.4. Deburring

C2.5. Surface treatment processes

# A. Classification







# A1. Theory

## Orthogonal cutting

- 2D
- Straight cutting edge
- Cutting edge  $\perp$  cutting direction




[eatandrelish.com](http://eatandrelish.com)



[www.tradebit.com](http://www.tradebit.com)


# A. Traditional technique



(a)


Speed motion (tool)

Feed motion (work)




(b)

Speed motion








(c)



(d)

# Cutting tool geometry








Rake angle  $\alpha > 0$

$\alpha = 0$


$\alpha < 0$



# ***EFFECT OF (back) RAKE ANGLE***


## Tool with negative rake:

- Has blunt but strong cutting edge
- Deforms material in front and below the tool
- Produces low shear angle



## Tool with positive rake:

- Has sharp yet fragile cutting edge
- Produces high shear angle
- Produces uniform chip





**Chip  
formation  
and BUE**



**0° rake**



**+45° rake**




**-20° rake**

Chip formation.wmv by Rick Steinard (Iscar)

<http://www.youtube.com/watch?v=mRuSYQ5Npek>


Built up edge.mpg by Phuc Pheo

<http://www.youtube.com/watch?v=uwh3ouvzSLk>



## A1.2. Mechanics: Merchant's circle and equation

- Orthogonal machining
- Cutting force
- Cutting power



$$\begin{aligned}\vec{R} &= \vec{F}_c + \vec{F}_t \\ &= \vec{F}_s + \vec{F}_n \\ &= \vec{F} + \vec{N}\end{aligned}$$

$$\mu = \tan\beta = \frac{F}{N}$$

$$\phi = 45^\circ + \frac{\alpha}{2} - \frac{\beta}{2}$$




# Cutting force measurement

Piezzo-dynamometer



# A2.1. Lathe operations




# Operations related to Turning

molotilo.com

Contour turning


Chamfering



Facing

Taper turning

Form turning



Cutoff

Threading

Boring


Drilling

Knurling


# A2.2. Similar processes

Hole making:


- 1.Center drill
- 2.Drill
- 3.Bore to size
- 4.Ream
- 5.Hone
- 6.Deburr




(a)




(b)




(c)



(d)



(e)



(f)

# Drill tap chart

Thread Size	Threads Per Inch	Thread Designation	Tap Drill Size	Decimal Equiv.	Theoretical % Thread Engagement	Major Diameter (inches)	Pitch Diameter (inches)	Minor Diameter (inches)	Stress Area of Installed Fastener (sq. in.)
1/2	24	UNC	16	0.1770	72%	0.2160	0.1889	0.171	0.0242
	28	UNF	14	0.1820	73%		0.1928	0.177	0.0258
	32	UNEF	3/16	0.1875	70%		0.1957	0.182	0.0270
1/4	20	UNC	7	0.2010	75%	0.2500	0.2175	0.196	0.0318
	28	UNF	3	0.2130	80%		0.2268	0.211	0.0364
	32	UNEF	7/32	0.2188	77%		0.2297	0.216	0.0379
5/16	18	UNC	F	0.2570	77%	0.3125	0.2764	0.252	0.0524
	20	UN	17/64	0.2656	72%		0.2800	0.258	0.0547
	24	UNF	I	0.2720	75%		0.2854	0.267	0.0581
	28	UN	J	0.2770	77%		0.2893	0.274	0.0606
	32	UNEF	9/32	0.2813	77%		0.2922	0.279	0.0625
3/8	16	UNC	5/16	0.3125	77%	0.3750	0.3344	0.307	0.0775
	20	UN	21/64	0.3281	72%		0.3425	0.321	0.0836
	24	UNF	Q	0.3320	79%		0.3479	0.330	0.0878
	28	UN	R	0.3390	78%		0.3518	0.336	0.0909
	32	UNEF	11/32	0.3438	77%		0.3547	0.341	0.0932

# A2.2. Milling








Table adjustments

Horizontal  
Peripheral  
/side milling




Vertical  
Face  
/end  
milling

# Milling analysis



Up milling  
(conventional milling)




Down milling  
(climb milling)

## A2.3. Broaching

- Add features to a drilled hole
- Make non-circular hole



Formed surface





(b)




## A2.4. Process plan

Step-by-step instructions to fabricate a part:


- Graphical illustration
- Tools, tool offset, tool sequence...
- Cutting speed, feed, depth of cut...
- Coolant / lubricant
- Deburring, packaging




# A2.5a. Cutting tools



(a) Solid tool




(b) Brazed insert




(c) Mechanically clamped insert


- ❑ Tool failure: wear, fracture, burnt...
- ❑ Tool life: machining distance, or time to replace a worn-out cutting tool

Uncoated tools




Coated tools





Crater wear  
(top view)



Flank wear (side view)

# Tool materials

Selection criteria: crack resistance (toughness)  
hardness  
wear resistance  
chemical resistance  
geometry  
cost, etc...

- HSS (high speed steel)
- WC (tungsten carbide)
- Coated WC
- CBN (cubic boron nitride)
- Diamond


# 8.3 Tool geometry

Important


- Nose radius
- Back rake angle

Effects

- Chip flow
- Surface integrity
- Tool life



(a)



(b) Tool signature:  $\alpha_b$ ,  $\alpha_s$ , ERA, SRA, ECEA, SCEA, NR

# Machinery's Handbook, 29<sup>th</sup> edition

## Table 3. Cutting Feeds and Speeds for Turning Stainless Steels

Material	Brinell Hardness	Tool Material											
		Uncoated HSS	Uncoated Carbide				Coated Carbide				Cermets		
			Hard		Tough		Hard		Tough				
		Speed (fpm)	f = feed (0.001 in./rev), s = speed (ft/min)										
Opt.	Avg.		Opt.	Avg.	Opt.	Avg.	Opt.	Avg.	Opt.	Avg.			
Free-machining stainless steel (Ferritic): 430F, 430FSe	135-185	110	f s	20 480	10 660	36 370	17 395	17 755	8 945	28 640	13 810	7 790	3 995
	135-185 225-275	100 80	f s	13 520	7 640	36 310	17 345			28 625	13 815	7 695	3 875
(Martensitic): 416, 416Se, 416 Plus X, 420F, 420FSe, 440F, 440FSe	135-185	110	f	13	7	36				28	13	7	3
	185-240	100	s	520	640	310				625	815	695	875
	275-325	60	f	13	7	36	17			28	13		
	375-425	30	s	210	260	85	135			130	165		
Stainless steels (Ferritic): 405, 409 429, 430, 434, 436, 442, 446, 502	135-185	90	f s	20 480	10 660	36 370	17 395	17 755	8 945	28 640	13 810	7 790	3 995
	135-185 225-275	75 65											
(Austenitic): 201, 202, 301, 302, 304, 304L, 305, 308, 321, 347, 348	135-185	70	f s	13 520	7 640	36 310	17 345			28 625	13 815	7 695	3 875
	135-175 175-225	95 85											
(Austenitic): 302B, 309, 309S, 310, 310S, 314, 316, 316L, 317, 330	135-185	70	f s	13 520	7 640	36 310	17 345			28 625	13 815	7 695	3 875
	135-175 175-225	95 85											
(Martensitic): 403, 410, 420, 501	275-325	55											
	375-425	35											
(Martensitic): 414, 431, Greek Ascology, 440A, 440B, 440C	225-275	55-60	f s	13 210	7 260	36 85	17 135			28 130	13 165	13 200†	7 230
	275-325 375-425	45-50 30											
(Precipitation hardening): 15-5PH, 17-4PH, 17-7PH, AF-71, 17-14CuMo, AFC-77, AM-350, AM-355, AM-362, Custom 455, HNM, PH13-8, PH14-8Mo, PH15-7Mo, Stainless W	150-200	60	f	13	7	36	17			28	13	13	7
	275-325	50	s	520	640	310	345			625	815	695	875
	325-375 375-450	40 25	f s	13 195	7 240	36 85	17 155						

# A2.5.b. Cutting fluid

## Why



- Heat generates at shear zone
- Friction at tool/chip interface

## Cutting fluid

- Coolant: water base + additives
- Lubricant: oil base + additives


## Latest technology: micromist

- Minimum fluid
- Most effective for external micromachining
- Environmental concern





Dry



Through tool flood



Flood



Mist

